C-585

39 A

C

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Friday 22nd Date May 1914

Depth from Surface, end of Shift ... 50 ft. in.
Depth from Surface, beginning of Shift 49 " "
Distance Drilled ..... 1 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
49		50		1		Solid granite

Total Drilled 1' } This should equal "DISTANCE DRILLED" above

Remarks
Had the same delay as yesterday and day before Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Hole finished

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Thursday 21st Date May 1914

Depth from Surface, end of Shift ... 49 ft. in.
Depth from Surface, beginning of Shift 47 " 8 "
Distance Drilled ..... 1 " 4 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
47	8	49		1	4	Solid Granite

Total Drilled 1'4" } This should equal "DISTANCE DRILLED" above

Remarks No Crevices.
Had the same delay as yesterday
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Wednesday 20th Date May 1914

Depth from Surface, end of Shift ... 47 ft. 8 in.
Depth from Surface, beginning of Shift 46 " 3 "
Distance Drilled ..... 1 " 5 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
46	3	47	8	1	5	Solid granite

Total Drilled 1'5" } This should equal "DISTANCE DRILLED" above

Remarks No crevices, but numerous small seams
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

(over)

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Tuesday 19th Date May 1914

Depth from Surface, end of Shift ... 46 ft. 3 in.
Depth from Surface, beginning of Shift 42 " 6 "
Distance Drilled ..... 3 " 9 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
42	6	44	2	1	8	Granite
44	2	44	4		2	Crevice
44	4	46	3	1	11	Solid granite

Total Drilled 3'9" } This should equal "DISTANCE DRILLED" above

Remarks What I mean by the term (Granite) is not solid but will make about 1 ft of core to 4 ft drilled Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Monday 18th Date May 1914

Depth from Surface, end of Shift ... 42 ft. 6 in.
Depth from Surface, beginning of Shift 36 " "
Distance Drilled ..... 6 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
36		41		5		Decayed granite
41		42	6	1	6	Granite

Total Drilled 6'6" } This should equal "DISTANCE DRILLED" above

Remarks No crevices
(see definition of granite on report of May 19th)
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Saturday 16th Date May 1914

Depth from Surface, end of Shift ... 36 ft. in.
Depth from Surface, beginning of Shift 31 " "
Distance Drilled ..... 5 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
31		36		5		Medium hard granite

Total Drilled 5' } This should equal "DISTANCE DRILLED" above

Remarks Had to drive another 10' of casing this A. M. total casing 30'
no crevices Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Had considerable delay to-day owing to the lack of proper fuel, the dry wood in the vicinety of the drill producing insufficient heat for the long line under which I am drilling

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Friday 15th Date May 1914

Depth from Surface, end of Shift ... 31 ft. ___ in.
Depth from Surface, beginning of Shift 20 " ___ "
Distance Drilled ..... 11 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
20		31		11		Decayed granite

Total Drilled 11' } This should equal "Distance Drilled" above

Remarks Formation getting harder

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 13,
Thursday 14th Date May 1914

Depth from Surface, end of Shift ... 20 ft. ___ in.
Depth from Surface, beginning of Shift ___ " ___ "
Distance Drilled ..... ___ " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
—		20		20		Decayed granite

Total Drilled 20' } This should equal "Distance Drilled" above

Remarks Put down 20' of casing to-day

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Monday 11th Date May 1914

Depth from Surface, end of Shift ... 70 ft. ___ in.
Depth from Surface, beginning of Shift 66 " 6 "
Distance Drilled ..... 3 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
66	6	70		3	6	Solid granite

Total Drilled 3'6" } This should equal "Distance Drilled" above

Remarks no crevices.
Started moving this evening

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Sunday 10th Date May 1914

Depth from Surface, end of Shift ... 66 ft. 6 in.
Depth from Surface, beginning of Shift 62 " 6 "
Distance Drilled ..... 4 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
62	6	64	4	1	10	Granite
64	4	66	6	2	2	Solid granite

Total Drilled 4' } This should equal "Distance Drilled" above

Remarks Struck solid granite at 64'4"
no crevices

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Saturday 9th Date May 1914

Depth from Surface, end of Shift ... 62 ft. 6 in.
Depth from Surface, beginning of Shift 55 " ___ "
Distance Drilled ..... 7 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
55		62	6	7	6	Granite

Total Drilled 7'6" } This should equal "Distance Drilled" above

Remarks No crevices, continues to get harder

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Friday 8th Date May 1914

Depth from Surface, end of Shift ... 55 ft. ___ in.
Depth from Surface, beginning of Shift 47 " 6 "
Distance Drilled ..... 7 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
47	6	55		7	6	Granite

Total Drilled 7'6" } This should equal "Distance Drilled" above

Remarks No crevices, getting harder

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Thursday 7th Date May 1914

Depth from Surface, end of Shift ... 47 ft. 6 in.
Depth from Surface, beginning of Shift 45 " " "
Distance Drilled ..... 2 " 6 "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
45		47		2		Decayed granite
47		47	6		6	Granite

Total Drilled 2' 6" } This should equal "DISTANCE DRILLED" above

Remarks Was compeled to drive 10' more casing total casing 30' (No crevices)
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Wednesday 6th Date May 1914

Depth from Surface, end of Shift ... 45 ft. in.
Depth from Surface, beginning of Shift 30 " " "
Distance Drilled ..... 15 " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
30		45		15		Decayed granite

Total Drilled 15' } This should equal "DISTANCE DRILLED" above

Remarks
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Tuesday 5th Date May 1914

Depth from Surface, end of Shift ... 30 ft. in.
Depth from Surface, beginning of Shift 10 " " "
Distance Drilled ..... 20 " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
10		30		20		Decayed granite

Total Drilled 20' } This should equal "DISTANCE DRILLED" above

Remarks Put down 10' more casing total casing 20'
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 12,
Monday 4th Date May 1914

Depth from Surface, end of Shift ... 10 ft. in.
Depth from Surface, beginning of Shift " "
Distance Drilled ..... " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
—		10		10		Decayed granite

Total Drilled 10' } This should equal "DISTANCE DRILLED" above

Remarks Rigged up this A. M. and put down 10' of casing P. M.
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

TRANSMITTAL NOTICE

From: Central Serials
To: Ron Silveira

Library material is forwarded herewith:

____ Circulation Unit
____ To be shelved in stacks
____ To be shelved on current shelves - first issue
____ Documents Unit
____ Language Center
____ Reference Unit
✓ Special Collections
____ (other)

Date: 3-29-68
Could this be part of railroad archives?

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 11,
Thursday Date April 30. 1914

Depth from Surface, end of Shift ... 48 ft. in.
Depth from Surface, beginning of Shift 46 " " "
Distance Drilled ..... " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
46		48		2		Solid Granite

Total Drilled 2. } This should equal "DISTANCE DRILLED" above

Remarks * Finished hole no 11. at noon and commenced moving to hole No. 12
Runner [illegible] Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Camp Dam.

Hole No. 11,

Wednesday **Date** April 29. **1914**

Depth from Surface, end of Shift ... 46 ft. ___ in.

Depth from Surface, beginning of Shift 36 " 6 "

Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
36	6	44		7	6	Decomposed granite
44		46		2		Solid granite

Total Drilled 9 {6 This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Camp Dam.

Hole No. 11,

Tuesday **Date** April 28. **1914**

Depth from Surface, end of Shift ... 36 ft. 6 in.

Depth from Surface, beginning of Shift 18 " "

Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
18		36	6	18	6	Hard pann & decomposed Granite

Total Drilled 18 {6 This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Camp Dam.

Hole No. 11,

Monday 27. **Date** April 27. **1914**

Depth from Surface, end of Shift ... 18 ft. ___ in.

Depth from Surface, beginning of Shift " "

Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
0		0		.5		Sand & Hard pann

Total Drilled .5 {6 This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Camp Camp.

Hole No. 10,

Friday **Date** April 24 **1914.**

Depth from Surface, end of Shift ... 49 ft. 6 in.

Depth from Surface, beginning of Shift 46 " "

Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
46		49	6	3	6	Solid granite

Total Drilled 3 {6 This should equal "DISTANCE DRILLED" above

Remarks Completed hole No. 10. We move the 27th and started to move to hole No. 11. this afternoon

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Camp Dam.

Hole No. 10,

Thursday **Date** April 23 **1914**

Depth from Surface, end of Shift ... 46 ft. ___ in.

Depth from Surface, beginning of Shift 34 " 6 "

Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
34	6	46		11	6	Soft Granite

Total Drilled 11 {6 This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Camp Dam.

Hole No. 10,

Wednesday **Date** April 22. **1914**

Depth from Surface, end of Shift ... 34 ft. 6 in.

Depth from Surface, beginning of Shift 27 " "

Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
27		34	6	7	6	Boulders, Sand & pebbles

Total Drilled 7.6 {6 This should equal "DISTANCE DRILLED" above

Remarks Had to drive casing farther down to cut sand & the flow of water out

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

See other side

The pump has giving us lots of trouble because it has not force enough to lift the gravel to top of the casing when we wash out.

Daily Report Drill No. 1, Day **Shift**

Location Power Dam

Hole No. 10,

Saturday **Date** April 18. **1917.**

Depth from Surface, end of Shift ... 27 ft. ____ in.

Depth from Surface, beginning of Shift 26 " ____ "

Distance Drilled ..... ____ " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
26		27		1		Boulders & Sand

Total Drilled 1 } This should equal "DISTANCE DRILLED" above

Remarks Drilled one foot but had to shut down to drive more casing on account of water coming up around casing.

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Power Dam

Hole No. 10.,

Friday **Date** April 17. **1917**

Depth from Surface, end of Shift ... 26 ft. ____ in.

Depth from Surface, beginning of Shift 23 " ____ "

Distance Drilled ..... ____ " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
23		26		3		Boulders & Hard pan.

Total Drilled 3. } This should equal "DISTANCE DRILLED" above

Remarks We drive more casing to twenty ft. on account of flow of gravel. The formation is anything to drill on account of small boulders

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Power D

Hole No. 10.,

Thursday **Date** April. 16. **1914**

Depth from Surface, end of Shift ... 23 ft. ____ in.

Depth from Surface, beginning of Shift 15 " ____ "

Distance Drilled ..... ____ " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
15		23		8		Hard pan & Boulders

Total Drilled 8 } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Power Dam

Hole No. 10,

Wednesday **Date** April 15. **1917**

Depth from Surface, end of Shift ... 15 ft. ____ in.

Depth from Surface, beginning of Shift ____ " ____ "

Distance Drilled ..... ____ " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
0		0		9		Sand
9		15		6		Hard pan & Boulders

Total Drilled 15 } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Power Camp

Hole No. 9,

Monday **Date** April 13. **1914**

Depth from Surface, end of Shift ... 44 ft. ____ in.

Depth from Surface, beginning of Shift 39 " 6 "

Distance Drilled ..... ____ " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
39	6	44		4	6	Solid Granite

Total Drilled 4 } 6 This should equal "DISTANCE DRILLED" above

Remarks This completes hole No. 9. There is no crevices or seepage in hole. The washing comes out of casing in the last shift. Will move to Hole No. 10. Tuesday. 14

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Camp.

Hole No. 9,

Saturday **Date** April 11. **1914**

Depth from Surface, end of Shift - - - 39 ft. 6 in.

Depth from Surface, beginning of Shift 28 " " "

Distance Drilled - - - - - - - " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
28		39	6	11	6	Decomposed Granite

Total Drilled 11' 6" } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Camp

Hole No. 9,

Friday **Date** April 10 **1914**

Depth from Surface, end of Shift - - - 36 ft. in.

Depth from Surface, beginning of Shift 13 " " "

Distance Drilled - - - - - - - " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
13		28		15		Hard Pann.

Total Drilled 15' } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Camp

Hole No. 9,

Thursday **Date** April 9th **1914**

Depth from Surface, end of Shift - - - 13 ft. in.

Depth from Surface, beginning of Shift " "

Distance Drilled - - - - - - - " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
0		7		7		Sand
7		13		6		Hard Pann.

Total Drilled 13 } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 9,

Wednesday **Date** April 5 **1914**

Depth from Surface, end of Shift - - - ft. in.

Depth from Surface, beginning of Shift " "

Distance Drilled - - - - - - - " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above

Remarks Sinking casing — note moving across river returned Apr 1st and Apr 8th

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Camp.

Hole No. 8.,

Tuesday **Date** 3/31/14 **1914**

Depth from Surface, end of Shift - - - 34 ft. in.

Depth from Surface, beginning of Shift 30 " 7 "

Distance Drilled - - - - - - - " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
30	7	34		3	5	Solid Granite

Total Drilled 3' 5" } This should equal "DISTANCE DRILLED" above

Remarks This completes hole No. 8. with solid Granite to thirty four feet

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Camp.

Hole No. 8.,

Monday **Date** 3/30 **1914**

Depth from Surface, end of Shift - - - 30 ft. 7 in.

Depth from Surface, beginning of Shift 28 " 7 "

Distance Drilled - - - - - - - " " "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
28	7	30	7	2		Solid Granite

Total Drilled 2 } This should equal "DISTANCE DRILLED" above

Remarks Reason for no more depth drilled, had to repair machinery so we could get coal ~~Runner~~ to drill

Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**
Location Pamo Camp.
Hole No. 8.,
Sunday **Date** 3/29. **1914**

Depth from Surface, end of Shift --- 28 ft. 7 in.
Depth from Surface, beginning of Shift 27 " 1 "
Distance Drilled - - - - - - - " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
27	1	28	7	1	6	Solid Granite.

Total Drilled 1½ { This should equal "DISTANCE DRILLED" above

Remarks Cause of no more debit drilled had to shut down to repair asentric on engine Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1. Day **Shift**
Location Pamo Camp.
Hole No. 8.,
Saturday **Date** 3/28. **1914**

Depth from Surface, end of Shift --- 27 ft. 1 in.
Depth from Surface, beginning of Shift 23 " 11 "
Distance Drilled - - - - - - - " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
23	11.	27	1	3	2.	Solid Granite.

Total Drilled 3" { 2. This should equal "DISTANCE DRILLED" above

Remarks The granite has been most valuant to hand no cracks or seams in this necks drilling. Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day, **Shift**
Location Pamo Dam.
Hole No. 8.,
Friday **Date** 3/27. **1914**

Depth from Surface, end of Shift --- 23 ft. 11 in.
Depth from Surface, beginning of Shift 21 " "
Distance Drilled - - - - - - - " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
21		23	11.	2	11.	Solid Granite

Total Drilled 2. 11" { This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**
Location Pamo Dam.
Hole No. 8.,
Thursday **Date** March 26. **1914**

Depth from Surface, end of Shift --- 21 ft. in.
Depth from Surface, beginning of Shift 18 " "
Distance Drilled - - - - - - - " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
18		21		3		Solid Granite

Total Drilled 3. { This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**
Location Pamo Dam.
Hole No. 8.,
Wednesday 25. **Date** March. **1914**

Depth from Surface, end of Shift --- 18 ft. in.
Depth from Surface, beginning of Shift 15 " "
Distance Drilled - - - - - - - " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
15		18		3		Solid granite

Total Drilled 3." { This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day. **Shift**
Location Pamo Dam.
Hole No. 8.,
Tuesday **Date** March 24. **1914**

Depth from Surface, end of Shift --- 15 ft. in.
Depth from Surface, beginning of Shift 13 " "
Distance Drilled - - - - - - - " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
13	5	15		1	7	Solid Granite

Total Drilled 1 { 7" This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 8,
Saturday 21st Date March 1914

Depth from Surface, end of Shift ... 13 ft. 5 in.
Depth from Surface, beginning of Shift 10 " " "
Distance Drilled ..... 3 " 5 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
10		12	10	2	10	Solid granite
12	10	13			2	Crevice
13		13	5		5	Solid granite

Total Drilled 3'5" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 8,
Friday 20th Date March 1914

Depth from Surface, end of Shift ... 10 ft. in.
Depth from Surface, beginning of Shift 7 " "
Distance Drilled ..... 3 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
7		10		3		Solid granite

Total Drilled 3' } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 8,
Thursday 19th Date March 1914

Depth from Surface, end of Shift ... 7 ft. in.
Depth from Surface, beginning of Shift " "
Distance Drilled ..... " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
—		3		3		Sand
3		5	6	2	6	Granite boulder
5	6	7		1	6	Solid granite

Total Drilled 7' } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Tuesday 17th Date March 1914

Depth from Surface, end of Shift ... 37 ft. in.
Depth from Surface, beginning of Shift 36 " 1 "
Distance Drilled ..... " 11 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
36	1	37			11	Solid granite

Total Drilled 11" } This should equal "Distance Drilled" above

Remarks Used up the remaining shot this A.M. Started moving this P.M.

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Monday 16th Date March 1914

Depth from Surface, end of Shift ... 36 ft. 1 in.
Depth from Surface, beginning of Shift 34 " 6 "
Distance Drilled ..... 1 " 7 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
34	6	36	1	1	7	Solid granite

Total Drilled 1'7" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Saturday 14th Date March 1914

Depth from Surface, end of Shift ... 34 ft. 6 in.
Depth from Surface, beginning of Shift 29 " 4 "
Distance Drilled ..... 5 " 2 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
29	4	31		1	8	Solid granite
31		33		2		Partly decayed granite
33		34	6	1	6	Solid granite

Total Drilled 5'2" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Friday 13th Date March 1914

Depth from Surface, end of Shift ... 29 ft. 4 in.
Depth from Surface, beginning of Shift 26 " 6 "
Distance Drilled ..... 2 " 10 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
26	6	29	4	2	10	Solid granite

Total Drilled 2' 10" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Thursday 12th Date March 1914

Depth from Surface, end of Shift ... 26 ft. 6 in.
Depth from Surface, beginning of Shift 24 " 6 "
Distance Drilled ..... 2 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
24	6	26	6	2		Solid granite

Total Drilled 2' } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Wednesday 11th Date March 1914

Depth from Surface, end of Shift ... 24 ft. 6 in.
Depth from Surface, beginning of Shift 22 " 4 "
Distance Drilled ..... 2 " 2 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
22	4	24	6	2	2	Solid granite

Total Drilled 2' 2" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam.
Hole No. 7,
Tuesday 10th Date March 1914

Depth from Surface, end of Shift ... 22 ft. 4 in.
Depth from Surface, beginning of Shift 20 " "
Distance Drilled ..... 2 " 4 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
20		22	4	2	4	Solid granite

Total Drilled 2' 4" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Monday 9th Date March 1914

Depth from Surface, end of Shift ... 20 ft. in.
Depth from Surface, beginning of Shift 17 " 6 "
Distance Drilled ..... 2 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
17	6	20		2	6	Solid granite

Total Drilled 2' 6" } This should equal "Distance Drilled" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Sunday 8th Date March 1914

Depth from Surface, end of Shift ... 17 ft. 6 in.
Depth from Surface, beginning of Shift 10 " "
Distance Drilled ..... 7 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
10		14	6	4	6	Decomposed granite
14	6	16	6	2		Granite Boulder
16	6	17	6	1		Decomposed granite

Total Drilled 7' 6" } This should equal "Distance Drilled" above

Remarks Sunk 5' 6" more casing making a total of 15' 6" of casing.

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 7,
Saturday 7th Date March 1914

Depth from Surface, end of Shift ... 10 ft. ___ in.
Depth from Surface, beginning of Shift ___ " ___ "
Distance Drilled ... ___ " ___ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
0		10		10		Decomposed granite

Total Drilled 10' } This should equal "DISTANCE DRILLED" above

Remarks Finished moving this A.M. put down 10' of casing this P.M.

Runner K. Steentock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 6,
Thursday 5th Date March 1914

Depth from Surface, end of Shift ... 44 ft. ___ in.
Depth from Surface, beginning of Shift 40 " ___ "
Distance Drilled ... 4 " ___ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
40		44		4		Solid granite

Total Drilled 4' } This should equal "DISTANCE DRILLED" above

Remarks Commenced moving this afternoon.

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 6,
Wednesday 4th Date March 1914

Depth from Surface, end of Shift ... 40 ft. ___ in.
Depth from Surface, beginning of Shift 26 " ___ "
Distance Drilled ... 14 " ___ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
26		36		10		Hard pan
36		40		4		Decomposed granite

Total Drilled 14' } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 6,
Tuesday 3rd Date March 1914

Depth from Surface, end of Shift ... 26 ft. ___ in.
Depth from Surface, beginning of Shift 12 " ___ "
Distance Drilled ... 14 " ___ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
12		26		14		Hard Pan

Total Drilled 14' } This should equal "DISTANCE DRILLED" above

Remarks No core, No crevice, washings still coming out at top of casing

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 6,
Monday 2nd Date March 1914

Depth from Surface, end of Shift ... 12 ft. ___ in.
Depth from Surface, beginning of Shift ___ " ___ "
Distance Drilled ... ___ " ___ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
0		12		12		Decomposed granite

Total Drilled 12' } This should equal "DISTANCE DRILLED" above

Remarks Finished moving this A.M. put down 12' of casing this P.M.

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 5,
Thursday 26th Date February 1914

Depth from Surface, end of Shift ... 40 ft. ___ in.
Depth from Surface, beginning of Shift 36 " ___ "
Distance Drilled ... 4 " ___ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
36		40		4		Solid granite

Total Drilled 4' } This should equal "DISTANCE DRILLED" above

Remarks This completes hole No 5

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 5,

Wednesday 25th **Date** February **191** 4

Depth from Surface, end of Shift ... 36 ft. ____ in.

Depth from Surface, beginning of Shift 29 " 6 "

Distance Drilled ..... 6 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
29	6	35		5	6	Decayed granite
35		36		1		Solid granite

Total Drilled 6' 6" } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 5,

Tuesday 24th **Date** February **191** 4

Depth from Surface, end of Shift ... 29 ft. 6 in.

Depth from Surface, beginning of Shift 19 " ____ "

Distance Drilled ..... 10 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
19		21		2		Solid granite
21		29	6	8	6	Decayed granite no core

Total Drilled 10' 6" } This should equal "DISTANCE DRILLED" above

Remarks Have not struck any crevices so far, water still bringing grindings to the surface

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 5,

Monday 23rd **Date** February **191** 4

Depth from Surface, end of Shift ... 19 ft. ____ in.

Depth from Surface, beginning of Shift 15 " ____ "

Distance Drilled ..... 4 " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
15		19		4		Solid granite

Total Drilled 4' } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 5,

Wednesday 18th **Date** February **191** 4

Depth from Surface, end of Shift ... 15 ft. ____ in.

Depth from Surface, beginning of Shift 6 " ____ "

Distance Drilled ..... 9 " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
6		15		9		Hard Pan granite no core

Total Drilled 9' } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 5,

Tuesday 17th **Date** February **191** 4

Depth from Surface, end of Shift ... 6 ft. ____ in.

Depth from Surface, beginning of Shift ____ " ____ "

Distance Drilled ..... ____ " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
0		6		6		Decomposed granite

Total Drilled 6' } This should equal "DISTANCE DRILLED" above

Remarks Finished moving A. M. started with casing P. M.

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day **Shift**

Location Pamo Dam

Hole No. 4,

Saturday 14th **Date** February **191** 4

Depth from Surface, end of Shift ... 42 ft. ____ in.

Depth from Surface, beginning of Shift 40 " ____ "

Distance Drilled ..... 2 " ____ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
40		42		2		Solid granite

Total Drilled 2' } This should equal "DISTANCE DRILLED" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Continued

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Friday 13th Date February 1914

Depth from Surface, end of Shift ... 40 ft. ___ in.
Depth from Surface, beginning of Shift 37 " 2 "
Distance Drilled ..... 2 " 10 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
37	2	40		2	10	Solid granite

Total Drilled 2' 10" } This should equal "Distance Drilled" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Thursday 12th Date February 1914

Depth from Surface, end of Shift ... 37 ft. 2 in.
Depth from Surface, beginning of Shift 33 " 8 "
Distance Drilled ..... 3 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
33	8	37	2	3	6	Solid granite

Total Drilled 3' 6" } This should equal "Distance Drilled" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Wednesday 11th Date February 1914

Depth from Surface, end of Shift ... 33 ft. 8 in.
Depth from Surface, beginning of Shift 28 " " "
Distance Drilled ..... 5 " 8 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
28		32		4		Partly decayed granite
32		38		1	8	Solid granite

Total Drilled 5' 8" } This should equal "Distance Drilled" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Tuesday 10th Date February 1914

Depth from Surface, end of Shift ... 28 ft. ___ in.
Depth from Surface, beginning of Shift 21 " " "
Distance Drilled ..... 7 " " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
21		26		5		Partly decayed granite
26		28		2		Solid Granite

Total Drilled 7' } This should equal "Distance Drilled" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Monday 9th Date February 1914

Depth from Surface, end of Shift ... 21 ft. ___ in.
Depth from Surface, beginning of Shift 17 " " "
Distance Drilled ..... 4 " " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
17		21		4		Decayed granite

Total Drilled 4' } This should equal "Distance Drilled" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Saturday 7th Date February 1914

Depth from Surface, end of Shift ... 17 ft. ___ in.
Depth from Surface, beginning of Shift 9 " " "
Distance Drilled ..... 8 " " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
9		17		8		Decayed granite

Total Drilled 8' } This should equal "Distance Drilled" above

Remarks

Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 4,
Friday 6th Date February 1914

Depth from Surface, end of Shift ... 9 ft. ___ in.
Depth from Surface, beginning of Shift ___ " ___ "
Distance Drilled ... ___ " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled 9 } This should equal "Distance Drilled" above

Remarks Finished moving this A.M. put down 9 ft of casing this P.M.
Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Tuesday 3rd Date February 1914

Depth from Surface, end of Shift ... 60 ft. ___ in.
Depth from Surface, beginning of Shift 56 " 6 "
Distance Drilled ... 3 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
56	6	60		3	6	Solid Granite

Total Drilled 3'6" } This should equal "Distance Drilled" above

Remarks This completes hole No 3, will comence moving to hole No 4 to-Morrow
Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Monday 2nd Date February 1914

Depth from Surface, end of Shift ... 56 ft. 6 in.
Depth from Surface, beginning of Shift 53 " 6 "
Distance Drilled ... 3 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
53	6	54	6	1		Broken up granite
54	6	56	6	2		Solid granite

Total Drilled 3' } This should equal "Distance Drilled" above

Remarks
Runner Peter Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Saturday 31st Date January 1914

Depth from Surface, end of Shift ... 53 ft. 6 in.
Depth from Surface, beginning of Shift 50 " ___ "
Distance Drilled ... 3 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
50		53	6	3	6	Solid Granite.

Total Drilled 3'6" } This should equal "Distance Drilled" above

Remarks
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Friday 30 Date January 1914

Depth from Surface, end of Shift ... 50 ft. ___ in.
Depth from Surface, beginning of Shift 46 " ___ "
Distance Drilled ... 4 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
46		50		4		Granite

Total Drilled 4' } This should equal "Distance Drilled" above

Remarks Struck small crevice at 47'5" contained flow of water
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Thursday 29 Date January 1914

Depth from Surface, end of Shift ... 46 ft. ___ in.
Depth from Surface, beginning of Shift 42 " 2 "
Distance Drilled ... 3 " 10 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
42	2	45	2	3		Solid Granite
45	2	45	6		4	Crevice
45	6	46			6	Solid Granite

Total Drilled 3'10" } This should equal "Distance Drilled" above

Remarks There appeared to be apparently no flow of water in aforesaid crevice
Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Wednesday 28 Date January 1914

Depth from Surface, end of Shift ... 42 ft. 2 in.
Depth from Surface, beginning of Shift 39 " " "
Distance Drilled ..... 3 " 2 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
39		42	2	3	2	Solid Granite

Total Drilled 3' 2" } This should equal "DISTANCE DRILLED" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Tuesday 27 Date January 1914

Depth from Surface, end of Shift ... 39 ft. in.
Depth from Surface, beginning of Shift 36 " 7 "
Distance Drilled ..... 2 " 5 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
36	7	39		2	5	Solid Granite.

Total Drilled 2' 5" } This should equal "DISTANCE DRILLED" above

Remarks Was delayed two hours this P.M. had trouble with the pump

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

over

Daily Report Drill No. 1, Day Shift
Location Pamo Dam.
Hole No. 3,
Monday 26 Date January 1914

Depth from Surface, end of Shift ... 36 ft. 7 in.
Depth from Surface, beginning of Shift 36 " 1 "
Distance Drilled ..... " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
36	1	36	7		6	Solid Granite

Total Drilled 6" } This should equal "DISTANCE DRILLED" above

Remarks Drilled one hour, was forced to suspend drilling by the high water

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

over

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Saturday 24th Date January 1914

Depth from Surface, end of Shift ... 36 ft. 1 in.
Depth from Surface, beginning of Shift 32 " 10 "
Distance Drilled ..... 3 " 3 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
32	10	36	1	3	3	Solid Granite

Total Drilled 3' 3" } This should equal "DISTANCE DRILLED" above

Remarks

Runner H. Steenbock Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Friday 23rd Date January 1914

Depth from Surface, end of Shift ... 32 ft. 10 in.
Depth from Surface, beginning of Shift 29 " 6 "
Distance Drilled ..... 3 " 4 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
29	6	32	10	3	4	Solid Granite

Total Drilled 3' 4" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lucey Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Thursday 22nd Date January 1914

Depth from Surface, end of Shift ... 29 ft. 6 in.
Depth from Surface, beginning of Shift 25 " 6 "
Distance Drilled ..... 4 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
25	6	29	6	4		Solid Granite

Total Drilled 4' } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lucey Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Water still high.

Had to make some changes in the pipe lines. also brought tubs + cans from camp in which to settle water for use in boiler comenced drilling at 9-30

Water raised very rapidly this A.M. was too dirty to use in boiler. would also clog up the pump.

P.M. water still raising threatens to undermine the boiler so we built a strong dyke around it.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 8,
Wednesday 21st Date January 1914

Depth from Surface, end of Shift ... 25 ft. 6 in.
Depth from Surface, beginning of Shift 23 " 10 "
Distance Drilled ..... 1 " 8 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
23	10	25	6	1	8	Solid Granite

Total Drilled 1' 8" } This should equal "DISTANCE DRILLED" above

Remarks Struck flow of water caused us much trouble, could not hold the shot on the bottom

Runner P. Lunz Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 8,
Tuesday 20 Date January 1914

Depth from Surface, end of Shift ... 23 ft. 10 in.
Depth from Surface, beginning of Shift 21 " 9 "
Distance Drilled ..... 2 " 1 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
21	9	23	10	2	1	Solid Granite

Total Drilled 2' 1" } This should equal "DISTANCE DRILLED" above

Remarks Repacked the pump.

Runner P. Lunz Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 9,
Monday 19th Date January 1914

Depth from Surface, end of Shift ... 21 ft. 9 in.
Depth from Surface, beginning of Shift 16 " 2 "
Distance Drilled ..... 5 " 7 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
16	2	16	8		6	Solid Granite.
16	8	16	10		2	Crevice
16	10	21	9	4	11	Solid Granite

Total Drilled 5' 7" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lunz Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Sunday 18th Date January 1914

Depth from Surface, end of Shift ... 16 ft. 2 in.
Depth from Surface, beginning of Shift 12 " 10 "
Distance Drilled ..... 3 " 4 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
12	10	16	2	3	4	Solid Granite

Total Drilled 3' 4" } This should equal "DISTANCE DRILLED" above

Remarks Made repairs on drilling machine.

Runner P. Lunz Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Saturday 17th Date January 1914

Depth from Surface, end of Shift ... 12 ft. 10 in.
Depth from Surface, beginning of Shift 6 " 6 "
Distance Drilled ..... 6 " 4 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
6	6	12	10	6	4	Solid Granite

Total Drilled 6' 4" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lunz Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Friday 16th Date January 1914

Depth from Surface, end of Shift ... 6 ft. 6 in.
Depth from Surface, beginning of Shift 2 " "
Distance Drilled ..... 4 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
2		5	9	3	9	Partly decomposed Granit
5	9	6			3	Crevice
6		6	6		6	Partly decomposed Granite

Total Drilled 4' 6" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lunz Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 3,
Thursday 15th Date January 1914

Depth from Surface, end of Shift ... 2 ft. ___ in.
Depth from Surface, beginning of Shift ___ " ___ "
Distance Drilled ... ___ " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
1	6	2			6	Solid Granite

Total Drilled 6" } This should equal "DISTANCE DRILLED" above

Remarks Finished moving and setting up started down with casing.

Runner P. Lundy Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. ___,
Wednesday 14th Date January 1914

Depth from Surface, end of Shift ... ___ ft. ___ in.
Depth from Surface, beginning of Shift ___ " ___ "
Distance Drilled ... ___ " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above

Remarks Moving drill to hole No 3.

Runner P. Lundy Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Tuesday 13th Date January 1914

Depth from Surface, end of Shift ... 71 ft. ___ in.
Depth from Surface, beginning of Shift 68 " 6 "
Distance Drilled ... 2 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
68	6	71		2	6	Solid Granite

Total Drilled 2' 6" } This should equal "DISTANCE DRILLED" above

Remarks Finished hole at noon. commenced moving to hole No 3. afternoon

Runner P. Lundy Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Monday 12th Date January 1914

Depth from Surface, end of Shift ... 68 ft. 6 in.
Depth from Surface, beginning of Shift 63 " 6 "
Distance Drilled ... 5 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
63	6	68	6	5		Solid Granite

Total Drilled 5' } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lundy Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Sunday 11th Date January 1914

Depth from Surface, end of Shift ... 63 ft. 6 in.
Depth from Surface, beginning of Shift 59 " 1 "
Distance Drilled ... 4 " 5 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
59	1	63	6	4	5	Solid Granite

Total Drilled 4' 5" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lundy Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Saturday 10th Date January 1914

Depth from Surface, end of Shift ... 59 ft. 1 in.
Depth from Surface, beginning of Shift 56 " ___ "
Distance Drilled ... 3 " 1 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
56		59	1	3	1	Solid Granite

Total Drilled 3' 1" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lundy Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Friday 9th Date January 1914

Depth from Surface, end of Shift ... 56 ft. ___ in.
Depth from Surface, beginning of Shift 49 " 9 "
Distance Drilled ..... 6 " 3 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
49	9	56		6	3	Solid Granite

Total Drilled 6' 3" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Thursday 8th Date January 1914

Depth from Surface, end of Shift ... 49 ft. 9 in.
Depth from Surface, beginning of Shift 45 " 3 "
Distance Drilled ..... 4 " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
45	3	49	9	4	6	Solid Granite

Total Drilled 4' 6" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Wednesday 7th Date January 1914

Depth from Surface, end of Shift ... 45 ft. 3 in.
Depth from Surface, beginning of Shift 42 " 5 "
Distance Drilled ..... 2 " 10 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
42	5	45	3	2	10	Solid Granite

Total Drilled 2' 10" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Tuesday 6th Date January 1914

Depth from Surface, end of Shift ... 42 ft. 5 in.
Depth from Surface, beginning of Shift 38 " 5 "
Distance Drilled ..... 4 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
38	5	42	5	4		Solid Granite

Total Drilled 4 } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Monday 5th Date January 1914

Depth from Surface, end of Shift ... 38 ft. 5 in.
Depth from Surface, beginning of Shift 32 " ___ "
Distance Drilled ..... 6 " 5 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
32		33		1		Solid Granite
33		33	6		6	Crevice
33	6	38	5	4	11	Solid Granite

Total Drilled 6' 5" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Sunday 4th Date January 1914

Depth from Surface, end of Shift ... 32 ft. ___ in.
Depth from Surface, beginning of Shift 27 " ___ "
Distance Drilled ..... 5 " ___ "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
27		32		5		Solid Granite

Total Drilled 5' } This should equal "DISTANCE DRILLED" above

Remarks

Runner P. Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Saturday 3rd Date January 1914

Depth from Surface, end of Shift ... 27 ft. ___ in.
Depth from Surface, beginning of Shift 25 " 2 "
Distance Drilled ..... 1 " 10 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
25	2	27		1	10	Broken Granite

Total Drilled 1' 10" } This should equal "DISTANCE DRILLED" above

Remarks Slow running owing to broken granite, had to pull out often

Runner P Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Friday 2nd Date January 1914

Depth from Surface, end of Shift ... 25 ft. 2 in.
Depth from Surface, beginning of Shift 24 " 8 "
Distance Drilled ..... " 6 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
24	8	25	2		6	Solid Granite

Total Drilled 6" } This should equal "DISTANCE DRILLED" above

Remarks Had to tamp the crevice full of sand before we could proceed

Runner P Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2
Thursday 1st Date January 1914

Depth from Surface, end of Shift ... 24 ft. 8 in.
Depth from Surface, beginning of Shift 22 " " "
Distance Drilled ..... 2 " 8 "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
22		24		2		Solid Granite
24		24	8		8	Crevice

Total Drilled 2' 8" } This should equal "DISTANCE DRILLED" above

Remarks

Runner P Lund Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Wednesday 31st Date Dec 1913

Depth from Surface, end of Shift, ... 22 ft. ___ in.
Depth from Surface, beginning of Shift 16 " " "
Distance Drilled ..... 6 " " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
16		19		3		Solid rock (granite)
19		19	2		2	crevice
19	2	22		2	10	

Total Drilled 6 } This should equal "DISTANCE DRILLED" above.

Remarks

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Tuesday 30th Date Dec, 1913

Depth from Surface, end of Shift, ... 16 ft. ___ in.
Depth from Surface, beginning of Shift 12 " " "
Distance Drilled ..... 4 " " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
12		16		4		Sand & boulders

Total Drilled 4 } This should equal "DISTANCE DRILLED" above.

Remarks Drilled through boulders blasted same

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 2,
Monday 29th Date Dec 1913

Depth from Surface, end of Shift, ... 12 ft. ___ in.
Depth from Surface, beginning of Shift — " " "
Distance Drilled ..... — " " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Put down 12 ft of 4" casing

Runner F Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo Dam

Hole No. 2,

Sunday 28th Date Dec. 1913

Depth from Surface, end of Shift, . . — ft. — in.

Depth from Surface, beginning of Shift — " — "

Distance Drilled . . . . . — " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled { This should equal "DISTANCE DRILLED" above.

Remarks Setting up drill

Runner Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo Dam Site

Hole No. 2,

Saturday 27th Date Dec. 1913

Depth from Surface, end of Shift, . . — ft. — in.

Depth from Surface, beginning of Shift — " — "

Distance Drilled . . . . . — " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled { This should equal "DISTANCE DRILLED" above.

Remarks Morning v setting up drill

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo Dam

Hole No. 1,

Friday Date Dec 26th 1913

Depth from Surface, end of Shift, . . 67 ft. — in.

Depth from Surface, beginning of Shift 63 " — "

Distance Drilled . . . . . 4 " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
63		65		2		Broken
65		67		2		Solid

Total Drilled 4 { This should equal "DISTANCE DRILLED" above.

Remarks Hole completed

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo Dam

Hole No.,

Thursday Date Dec 25th 1913

Depth from Surface, end of Shift, . . — ft. — in.

Depth from Surface, beginning of Shift — " — "

Distance Drilled . . . . . — " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled { This should equal "DISTANCE DRILLED" above.

Remarks Trip to Ramona for mail v pay bills (Looking after drill during flood)

Runner F. Miller. Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo Dam

Hole No. 1

Wednesday 24th Date December 1913

Depth from Surface, end of Shift, . . 63 ft. — in.

Depth from Surface, beginning of Shift 59 " — "

Distance Drilled . . . . . 4 " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
59		63		4		Solid granite

Total Drilled 4 { This should equal "DISTANCE DRILLED" above.

Remarks

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo Dam

Hole No. 1,

Tuesday 23rd Date December 1913

Depth from Surface, end of Shift, . . 59 ft. — in.

Depth from Surface, beginning of Shift 56 " — "

Distance Drilled . . . . . 3 " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
56		59		3		Solid granite

Total Drilled 3 { This should equal "DISTANCE DRILLED" above.

Remarks Had to shovel sand from around drill after the flood

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. 1,
Monday Date Dec. 22nd 1913

Depth from Surface, end of Shift, . . 56 ft. ____ in.
Depth from Surface, beginning of Shift 53 " ____ "
Distance Drilled . . . . . 3 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
53		56		3		Solid granite

Total Drilled 3 } This should equal "DISTANCE DRILLED" above.

Remarks Repaired road to get team over acc. of washout
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam
Hole No. ____,
Sunday 21st Date December 1913

Depth from Surface, end of Shift, . . 13 ft. ____ in.
Depth from Surface, beginning of Shift ____ " ____ "
Distance Drilled . . . . . 13 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
						Drove 3" casing

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Putting down water well for camp
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Saturday 20th Date December 1913

Depth from Surface, end of Shift, . . ____ ft. ____ in.
Depth from Surface, beginning of Shift ____ " ____ "
Distance Drilled . . . . . ____ " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
						Shut down raining

Total Drilled — } This should equal "DISTANCE DRILLED" above.

Remarks Repaired blowed out boiler to clean same (helper laid off)
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. 1,
Friday 19th Date December 1913

Depth from Surface, end of Shift, . . 53 ft. ____ in.
Depth from Surface, beginning of Shift 50 " ____ "
Distance Drilled . . . . . 3 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
50		53		3		Solid granite

Total Drilled 3 } This should equal "DISTANCE DRILLED" above.

Remarks Water continues to flow from hole outside casing delayed by steam
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. 1,
Thursday Date Dec. 18th 1913

Depth from Surface, end of Shift, . . 50 ft. ____ in.
Depth from Surface, beginning of Shift 46 " ____ "
Distance Drilled . . . . . 4 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
46		50		4		Solid granite

Total Drilled 4 } This should equal "DISTANCE DRILLED" above.

Remarks
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Wednesday Date December 17th 1913

Depth from Surface, end of Shift, . . 46 ft. ____ in.
Depth from Surface, beginning of Shift 43 " ____ "
Distance Drilled . . . . . 3 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
43		46		3		Solid granite vertical seam at 45 ft.

Total Drilled 3 } This should equal "DISTANCE DRILLED" above.

Remarks Flow of water at 45 ft interfers with drilling
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Tuesday Date Dec 16th 1913

Depth from Surface, end of Shift, . . — ft. — in.
Depth from Surface, beginning of Shift — " — "
Distance Drilled . . . . . — " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Taking inventory and sending off same

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Monday Date Dec 15th 1913

Depth from Surface, end of Shift, . . 43 ft. — in.
Depth from Surface, beginning of Shift 40 " — "
Distance Drilled . . . . . 3 " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
40		43		3		Solid granite

Total Drilled 3 } This should equal "DISTANCE DRILLED" above.

Remarks Delayed by injector getting out of order, fixed same

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. 1,
Sunday Date Dec 14th 1913

Depth from Surface, end of Shift, . . 40 ft. — in.
Depth from Surface, beginning of Shift 36 " — "
Distance Drilled . . . . . 4 " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
36		40		4		Solid granite

Total Drilled 4 } This should equal "DISTANCE DRILLED" above.

Remarks

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. 1,
Saturday Date Dec 13th 1913

Depth from Surface, end of Shift, . . 36 ft. — in.
Depth from Surface, beginning of Shift 31 " — "
Distance Drilled . . . . . 5 " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
31		33		2		Solid granite
33		35		2		Vertical seams
35		36		1		Solid granite

Total Drilled 5 } This should equal "DISTANCE DRILLED" above.

Remarks Struck flow of water 33 ft same comes up outside 3" pipe

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. 1,
Friday Date Dec 12th 1913

Depth from Surface, end of Shift, . . — ft. — in.
Depth from Surface, beginning of Shift — " — "
Distance Drilled . . . . . — " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Setting up new pump and pickering same

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. 1,
Thursday Date Dec. 11th 1913

Depth from Surface, end of Shift, . . — ft. — in.
Depth from Surface, beginning of Shift — " — "
Distance Drilled . . . . . — " — "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
						3 men cutting wood

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Back from city with new pump team half day to haul pump & wood

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Wednesday Date Dec 10th 1913

Depth from Surface, end of Shift, . . ____ ft. ____ in.
Depth from Surface, beginning of Shift ____ " ____ "
Distance Drilled . . . . . ____ " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
						3 men cutting wood

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks In city in reference to new pump.
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Tuesday Date Dec 9th 1913

Depth from Surface, end of Shift, . . ____ ft. ____ in.
Depth from Surface, beginning of Shift ____ " ____ "
Distance Drilled . . . . . ____ " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
						3 men cutting wood

Total Drilled ____ } This should equal "DISTANCE DRILLED" above.

Remarks Team to haul pump to Ramona to go to San Diego
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Monday Date Dec 8th 1913

Depth from Surface, end of Shift, . . ____ ft. ____ in.
Depth from Surface, beginning of Shift ____ " ____ "
Distance Drilled . . . . . ____ " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Pump out of order
Inspection by Hayward Goldman
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Saturday Date Dec 6th 1913

Depth from Surface, end of Shift, . . 31 ft. ____ in.
Depth from Surface, beginning of Shift 27 " ____ "
Distance Drilled . . . . . 4 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
27		31		4		Solid granite

Total Drilled 4 } This should equal "DISTANCE DRILLED" above.

Remarks Pump not working right overhauling same
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Friday Date Dec 5th 1913

Depth from Surface, end of Shift, . . 27 ft. ____ in.
Depth from Surface, beginning of Shift 26 " ____ "
Distance Drilled . . . . . 1 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
26		27		1		Solid granite

Total Drilled 1 } This should equal "DISTANCE DRILLED" above.

Remarks Repaired pressure gear valve made new trays and fitted same
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.
Drill crew carried wood.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Thursday Date Dec 4th 1913

Depth from Surface, end of Shift, . . 26 ft. ____ in.
Depth from Surface, beginning of Shift 22 " ____ "
Distance Drilled . . . . . 4 " ____ "

FROM FEET	IN.	TO FEET	IN.	FEET	IN.	FORMATION
22		26		4		Solid granite

Total Drilled 4 } This should equal "DISTANCE DRILLED" above.

Remarks Delayed account of steam
Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Wednesday Date Dec. 3rd 1913

Depth from Surface, end of Shift, . . 22 ft. in.
Depth from Surface, beginning of Shift 15 " "
Distance Drilled . . . . . 4 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
15		22		4		Slightly broken Hard Granite

Total Drilled 4 } This should equal "DISTANCE DRILLED" above.

Remarks Delayed by bad fuel no steam

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Tuesday Date Dec 2nd 1913

Depth from Surface, end of Shift, . . 18 ft. in.
Depth from Surface, beginning of Shift 13 " "
Distance Drilled . . . . . 5 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
13		17		4		Solid granite
17		17	6		6	crevice
17	6	18			6	Solid granite

Total Drilled 5 } This should equal "DISTANCE DRILLED" above.

Remarks Drill rods dropped 6" through crevice

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site B.
Hole No. 1,
Monday Date Dec. 1st 1913

Depth from Surface, end of Shift, . . 13 ft. in.
Depth from Surface, beginning of Shift 10 " "
Distance Drilled . . . . . 3 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
10		13		3		Hard solid granite

Total Drilled 3 } This should equal "DISTANCE DRILLED" above.

Remarks Delayed by lack of steam bad fuel

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam Site
Hole No. 1,
Saturday Date Nov 29th 1913

Depth from Surface, end of Shift, . . 10 ft. in.
Depth from Surface, beginning of Shift 7 " "
Distance Drilled . . . . . 3 " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION
7		10		3		Solid granite
Surface		rock		7		Water 3'6" and 3'6"

Total Drilled 3 } This should equal "DISTANCE DRILLED" above.

Remarks Put casing down to rock and drilled down same 15"

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. ,
Friday Date Nov 28th 1913

Depth from Surface, end of Shift, . . ft. in.
Depth from Surface, beginning of Shift " "
Distance Drilled . . . . . " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Setting up Drill

Runner Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift
Location Pamo Dam site B.
Hole No. ,
Thursday Date Nov 27th 1913

Depth from Surface, end of Shift, . . ft. in.
Depth from Surface, beginning of Shift " "
Distance Drilled . . . . . " "

FROM FEET	FROM IN.	TO FEET	TO IN.	FEET	IN.	FORMATION

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Setting Drill

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

853.6
17
836.6

Daily Report Drill No. 1, Day Shift

Location Pamo. Dam site B.

Hole No. ,

Wednesday Date Nov. 26th 1913

Depth from Surface, end of Shift, . . ft. in.

Depth from Surface, beginning of Shift " "

Distance Drilled . . . . . " "

FROM		TO				FORMATION
FEET	IN.	FEET	IN.	FEET	IN.	

Total Drilled } This should equal "DISTANCE DRILLED" above.

Remarks Placing machinery on Dam site

Runner F. Miller Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Daily Report Drill No. 1, Day Shift

Location Pamo. Dam, site B.

Hole No. 1 (Bed of stream)

Tuesday Date Nov. 25th 1913

Depth from Surface, end of Shift, . . — ft. in.

Depth from Surface, beginning of Shift — " "

Distance Drilled . . . . . " "

FROM		TO				FORMATION
FEET	IN.	FEET	IN.	FEET	IN.	
						—

Total Drilled — } This should equal "DISTANCE DRILLED" above.

Remarks Hauling machinery from camp (2) to Dam site B.

Runner F. Miller. Foreman

Report additional remarks, causes of delays, accidents, etc., on other side of this sheet. One of these reports for each shift.

Ed Fletcher Papers

1870-1955

MSS.81

Box: 48 Folder: 2

Business Records - Water Companies - Volcan Land and Water Company - San Dieguito System - San Dieguito Mutual Water Company - San Dieguito/ Pamo Dam - Daily reports: drilling at Pamo Dam site

Copyright: UC Regents

Use: This work is available from the UC San Diego Libraries. This digital copy of the work is intended to support research, teaching, and private study.

Constraints: This work is protected by the U.S. Copyright Law (Title 17, U.S.C.). Use of this work beyond that allowed by "fair use" requires written permission of the UC Regents. Permission may be obtained from the UC SanDiego Libraries department having custody of the work (http://libraries.ucsd.edu/collections/mscl/). Responsibility for obtaining permissions and any use and distribution of this work rests exclusively with the user and not the UC San Diego Libraries.